



### Specifications

Model	Line Voltage (VAC)	Armature Voltage Range (VDC)	Continuous Armature Current (Amps)	Motor Continuous HP Range
PWP100-2	115	0 - 130	2.0	1/20 - 1/4
PWP100-5	115	0 - 130	5.0	1/4 - 3/4
PWP100-10	115	0 - 130	10.0*	1/4 - 1 1/2

\* Heat sink kit 223-0159 must be used when the continuous output current is over 5 amps.


AC Line Source	115 VAC ± 10%, 50/60 Hz, 1Ø
DC Source	100 - 160 VDC
Acceleration Time Range	0.5 - 6 seconds
Deceleration Time Range	coast to stop - 6 seconds
Input Impedance (S1 to S2)	10K ohms
Analog Input Signal Range (isolated)	0 - 10 VDC
Form Factor	1.05
Load Regulation	1.0% of base speed or better
Speed Rang	80:1
Maximum Vibration 0 - 50 Hz (>50 Hz)	0.5G (0.1G)
Surrounding Air Temperature Range	50 - 104°F / 10 - 40°C
Weight (PWP100-2)	0.60 lbs / 0.27 kg
(PWP100-5, PWP100-10)	0.70 lbs / 0.32 kg
Safety Certifications	UL Recognized, File # E132235 CSA Certified Component, File # LR41380

### Safety Warnings

#### READ ALL SAFETY WARNINGS BEFORE INSTALLING THIS EQUIPMENT

- **DO NOT INSTALL, REMOVE OR REWIRE THIS EQUIPMENT WITH POWER APPLIED.** Have a qualified electrical technician install, adjust and service this equipment. Follow the National Electrical Code and all other applicable electrical and safety codes, including the provisions of the Occupational Safety and Health Act (OSHA), when installing equipment.
- **Circuit potentials are at 115 VAC above earth ground.** Avoid direct contact with the printed circuit board or with circuit elements to prevent the risk of serious injury or fatality. Use approved personal protection equipment and insulated tools if working with power applied. Use a non-metallic screwdriver for adjusting the calibration trim pots.
- Reduce the chance of an electrical fire, shock, or explosion by using proper grounding techniques, over-current protection, thermal protection and enclosure. Follow sound maintenance procedures.
- **It is strongly recommended to install a master power switch in the line voltage input.** The switch contacts should be rated for 125 VAC and 200% of motor nameplate current.
- **Removing AC line power is the only acceptable method for emergency stopping.** Do not use braking, decelerating, or coasting to a stop for emergency stopping. They may not stop a drive that is malfunctioning.
- Line starting and stopping (applying and removing AC line voltage) is recommended for infrequent starting and stopping of a drive only. Braking, decelerating to minimum speed, or coasting to a stop is recommended for frequent starts and stops. Frequent starting and stopping can produce high torque. This may cause damage to motors.
- **Do not disconnect any of the motor leads from the drive** unless power is removed or the drive is disabled. Opening any one lead while the drive is running may damage the drive.
- Under no circumstances should power and logic level wires be bundled together.
- Be sure potentiometer tabs do not make contact with the potentiometer's body. Grounding the input may cause damage to the drive.
- This product does not have internal solid state motor overload protection. It does not contain speed-sensitive overload protection, thermal memory retention, or provisions to receive and act upon signals from remote devices for over temperature protection. If motor protection is needed in the end-use product, it needs to be provided by additional equipment in accordance with NEC standards.

### Dimensions



MODEL	DIMENSION "A" HEIGHT
PWP100-2	1.77 [45]
PWP100-5	2.36 [60]
PWP100-10	2.88 [73]

ALL DIMENSIONS IN INCHES [MILLIMETERS]

### Installation

#### Mounting

- Components are sensitive to electrostatic discharge. Avoid direct contact with the circuit board. Hold the drive by the chassis or heat sink only.
- Protect from dirt, moisture, and accidental contact.
- Provide sufficient room for access to the terminals and calibration trim pots.
- Mount away from heat sources. Operate within the surrounding air temperature range.
- Prevent loose connections by avoiding excessive vibration.
- Mount in either a horizontal or vertical plane. Six 0.19" (5 mm) wide slots in the chassis accept #8 pan head screws.
- The chassis should be earth grounded. Use a star washer beneath the head of at least one of the mounting screws to penetrate the anodized chassis surface and to reach bare metal.

**Heat Sinking:** The PWP100-10 requires an additional heat sink when the continuous armature current is above 5 amps. Use heat sink kit part number 223-0159. Use a thermally conductive heat sink compound (such as Dow Corning 340® Heat Sink Compound) between the chassis and the heat sink surface for optimal heat transfer.

**Wiring:** Use 18 - 24 AWG wire for logic wiring. Use 14 - 16 AWG wire for AC line and motor wiring.

**Shielding Guidelines:** As a general rule, it is recommended to shield all conductors. If it is not practical to shield power conductors, it is recommended to shield all logic-level leads. If shielding of logic-level leads is not practical, the user should twist all logic leads with themselves to minimize induced noise. It may be necessary to earth ground the shielded cable. If noise is produced by devices other than the drive, ground the shield at the drive end. If noise is generated by the drive, ground the shield at the end away from the drive. Do not ground both ends of the shield.

**Fusing:** Use fast acting fuses rated for 125 VAC or higher and 150% of the maximum armature current. Fuse the HOT leg of the AC line.

### Connections

#### Input Power

Connect the AC line power leads to terminals L1 and L2. It is recommended to use a double-pole, single-throw master power switch. The switch should be rated at a minimum of 125 VAC and 200% of motor current. The drives can also be powered by a DC source connected to terminals +DC IN (positive) and -DC IN (negative).

#### Motor


Connect the DC armature leads to terminals A1 and A2. If the motor does not spin in the desired direction, power down the drive and reverse these connections.

#### Speed Potentiometer

Use a 10K ohm, 1/4 W potentiometer for speed control. Connect the counter-clockwise end of the potentiometer to S1, the wiper to S2, and the clockwise end to S3. If the potentiometer works inversely of desired functionality, (i.e. to increase motor speed, you must turn the potentiometer counterclockwise), power off the drive and swap the S1 and S3 connections.

#### Analog Input Signal Range

Instead of using a speed adjust potentiometer, PWP100 series drives may be wired to follow a 0-5 VDC analog signal. The analog signal must be ungrounded (floating). Connect the signal common (-) to S1 and the signal input (+) to S2.



# Startup

## STARTUP


- Verify that no foreign conductive material is present on the printed circuit board.

1. Turn the speed adjust potentiometer full counterclockwise (CCW).
2. Apply AC line voltage.
3. Slowly advance the speed adjust potentiometer clockwise (CW). The motor slowly accelerates as the potentiometer is turned CW. Continue until the desired speed is reached.
4. Remove the source voltage from the drive to coast the motor to a stop.

# Operation


## Run/Stop Switch - Coast or Decelerate to Zero Speed

Either of the two options shown below can be used to coast a motor to zero speed. Opening Switch Option #1, or closing Switch Option #2, decelerates the motor from set speed to zero speed at a rate determined by the ACCEL/DECEL trim pot setting. Closing Switch Option #1, or opening Switch Option #2, will accelerate the motor to set speed at a rate determined by the ACCEL/DECEL trim pot setting. If two methods of starting and stopping are required, both options can be used concurrently.




## Run/Stop Switch - Dynamic Brake to Zero Speed

Dynamic braking may be used to rapidly stop a motor. For the RUN/BRAKE switch, use a two pole, two position switch rated for at least the armature voltage rating and 150% of the armature current rating. For the dynamic brake resistor, use a 40 watt minimum, high power, wirewound resistor. Sizing the dynamic brake resistor depends on load inertia, motor voltage, and braking time. Use a lower-value, higher-wattage dynamic brake resistor to stop a motor more rapidly. Recommended value is 15 ohms for a 130 VDC motor.



## Reversing with a Dynamic Brake

A dynamic brake may be used when reversing the motor direction. Use a three pole, three position relay or two double-pole, double-throw switches. Contacts should be rated for at least the armature voltage rating and 150% of the armature current rating. For the dynamic brake resistor, use a 40 watt minimum, high power, wirewound resistor. Sizing the dynamic brake resistor depends on load inertia, motor voltage, and braking time. Use a lower-value, higher-wattage dynamic brake resistor to stop a motor more rapidly. Recommended value is 15 ohms for a 130 VDC motor. **The motor must come to a complete stop before changing directions.**



3P3T Relay for Forward/Brake/Reverse

Two DPDT Switches for Independent Run/Brake & Forward/Reverse Switches

# Calibration

**Maximum Speed (MAX SPEED):** The MAX SPEED setting determines the maximum motor speed when the speed adjust potentiometer is set for maximum speed. To calibrate the MAX SPEED:

1. Set the MAX SPEED trim pot full CCW.
2. Set the speed adjust potentiometer for maximum speed.
3. Adjust the MAX SPEED trim pot until the desired maximum speed is reached.

**Torque (CURRENT LIMIT):** The CURRENT LIMIT setting determines the maximum torque for accelerating and driving the motor. To calibrate the CURRENT LIMIT:

1. With the power disconnected from the drive, connect a DC ammeter in series with the armature.
2. Set the CURRENT LIMIT trim pot to minimum (full CCW).
3. Set the speed adjust potentiometer to maximum speed (full CW).
4. Carefully lock the motor armature. Be sure that the motor is firmly mounted.
5. Apply line power. The motor should be stopped.
6. Slowly adjust the CURRENT LIMIT trim pot CW until the armature current is 150% of motor rated armature current. **Continuous operation beyond this rating may damage the motor.**
7. Turn the speed adjust potentiometer CCW.
8. Remove line power.
9. Remove the stall from the motor.
10. Remove the ammeter in series with the motor armature if it is no longer needed.

**IR Compensation (IR COMP):** The IR COMP setting determines the degree to which motor speed is held constant as the motor load changes. To calibrate the IR COMP:

1. Set the IR COMP trim pot full CCW.
2. Increase the speed adjust potentiometer until the motor runs at midspeed without load. A handheld tachometer may be used to measure motor speed.
3. Load the motor armature to its full load armature current rating. The motor should slow down.
4. While keeping the load on the motor, rotate the IR COMP trim pot until the motor runs at the speed measured in step 2. If the motor oscillates (overcompensation), the IR COMP trim pot may be set too high (CW). Turn the IR COMP trim pot CCW to stabilize the motor.
5. Unload the motor.

**Acceleration & Deceleration (ACCEL/DECEL):** The ACCEL/DECEL setting determines the time the motor takes to ramp to a different speed. ACCEL/DECEL is factory set for the shortest time (full CCW). To calibrate the ACCEL/DECEL, turn the ACCEL/DECEL trim pot CW to increase the acceleration and deceleration time or turn it CCW to decrease the acceleration and deceleration time.